

APPENDIX D

PHOTOGRAPHS





Photograph 1: View of the inactive compressed natural gas ("CNG") refueling station located in the northeast corner of the subject property. The masonry structure houses three (3) 48-inch inner diameter spherical CNG tanks, a compressor, a gas dryer, and a small control room. A second compressor, a 150-horespower compressor that replaced the compressor housed within the structure as the primary compressor in 1999, and an electrical switchgear box are located on a concrete pad on the northwest side of this structure. Two (2) CNG dispenser pump islands are located southwest of the structure. This refueling station was previously operated by PAF Fueling Systems, Inc., which refueled the CNG vehicle fleet previously operated by the Philadelphia Gas Works ("PGW").

<u>Photograph 2:</u> View of the three (3) 48-inch inner diameter spherical CNG tanks located within the CNG refueling station structure. The tanks were observed to be in good condition.




<u>Photograph 3:</u> View of the gas dryer within the CNG refueling station structure.




PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT

Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122



Photograph 4: View of the compressor located within the CNG refueling station structure.



<u>Photograph 5:</u> View of the 150-horsepower compressor located on a concrete pad just outside the northwest corner of the CNG refueling station structure.




Photograph 6: View of the natural gas line by the northeast corner of the structure that supplies natural gas to the refueling station.



PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT

Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122



<u>Photograph 7:</u> View of the southeast side of the CNG refueling station structure.



<u>Photograph 8:</u> Interior view of the control room/parts storage shop in the northeast corner of the CNG refueling station structure.



<u>Photograph 9:</u> View of the parking lot along the west side of the subject property. The Southeastern Pennsylvania Transportation Authority ("SEPTA") owns a right-of-way that extends 25 feet east of the stone retaining wall visible on the right in this photograph.




PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT


Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122



Photograph 10: View of the asphalt paved parking lot on the subject property.



Photograph 11: View of a small guard shack located along the eastern border of the subject property.



<u>Photograph 12:</u> View of a storage yard operated by PGW's Transportation Department located adjacent to the north of the subject property across West Norris Street.



PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT

Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122

SITE PHOTOGRAPHS

Job No.

PHILDC 1001.01


Date Taken: March 1, 2010



<u>Photograph 13:</u> View of a vacant lot and residential dwellings located adjacent to the northeast of the subject property across the intersection of West Norris Street and North 9th Street.



<u>Photograph 14:</u> View of vacant lots and residential dwellings located adjacent to the east of the subject property across North 9th Street.



<u>Photograph 15:</u> View of PGW's Transportation Department garage located adjacent to the southeast of the subject property at the southeast corner of West Berks Street and North 9th Street.




PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT

Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122



Photograph 16: View of the PGW office building and garage located adjacent to the south of the subject property across West Berks Street.



Photograph 17: View of the Temple University train station entrance and elevated lines of SEPTA's R-6 Regional Rail line located adjacent to the southwest corner f the subject property.




PENNONI ASSOCIATES INC. 3001 MARKET STREET PHILADELPHIA, PENNSYLVANIA 19104 PHASE I ENVIRONMENTAL SITE ASSESSMENT

Former Philadelphia Gas Works Refueling Station North 9th Street and West Berks Street Philadelphia, Pennsylvania 19122

APPENDIX E

HAZARDOUS MATERIALS BUILDING SURVEY



From: 8568584503 To: Jim Amendt Page: 1/3 Date: 3/1/2010 11:51:13 PM

Asbestos • Lead • Environmental • Materials & Indoor Air Analysis

EMSL Analytical, Inc. 107 Haddon Ave. Westmont, NJ 08108

Phone: (856) 858-4800 Fax: (856) 858-4960

Web: http://www.emsl.com Email: westmontasblab@EMSL.com

FACSIMILE TRANSMITTAL SHEET

To: Jim Amendt From: EMSL Analytical, Inc.

Company: Pennoni Associates, Inc. Date: March 01, 2010

Fax Number: (856) 547-1039 PAGES INCLUDING COVER: 3

Phone Number: (856) 547-0505

RE: Analysis Results for Order(s) 041003978

The following report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on the following date(s):

3/1/2010 5:30:00PM

Notice: This information may contain privileged and confidential information and is solely for the use of the

sender's intended recipient(s). If you received this information in error, please notify the sender and delete

all copies. Thank you.

EMSL Analytical, Inc. News

EMSL PRODUCTS Online Training New Lab Services at EMSL

MONTHLY SPECIALS
Air-o-Cell (50pk) \$199.00

www.EMSLTraining.com
Chinese Drywall Testing

PCM Cassettes \$24(10+bx) | CIE | PCB's

TEM Cassettes \$39(10+bx)

CMI

Rapid Pathogen Detection by Real

CIAQM

Microbiology for the IAQ Professional

Radon

Microbiology for the IAQ Professional

HVAC for the IAQ Professional

PUMP BLOWOUT SALE

HVAC for the IAQ Professional

Westmont, NJ Lab Open Saturday
Asbestos, Lead, and Mold Analysis!

Coduct #870610 Online Sampling Videos 1-800-220-3675 East Coast

www.EMSL.tv

Product #8706105

H/D Diaphragm Pump Kit \$425

IAQ INSTRUMENT DEALS

Product #8703003

Protimeter Mini Moisture Meter \$175

Product #8704013

BIOS Defender 510-H \$1299

If you have any questions, please do not hesitate to contact us at (856) 858-4800.

VISIT OUR WEBSITE AT http://www.emsl.com

Please tell us how we are doing by going to the survey at http://www2.emsl.com/custsurvey/?fromregion=eastcoast



Attn: Jim Amendt

Pennoni Associates, Inc.

515 Grove Street Suite 1B

Haddon Heights, NJ 08035

Fax (856) 547-1039

Project: PGW/PHILDC-1001.01/9TH NORRIS ST./REFUELING STA

Phone: (856) 547-0505

EMSL Proj:

Customer ID:

Customer PO:

EMSL Order:

Received:

Analysis Date:

3/1/2010

PENN50

041003978

03/01/10 5:30 PM

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description			Non-Asbestos		Asbestos
		Appearance	%	Fibrous	% Non-Fibrous	% Type
01 041003978-0001	FLOOR TILE	White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
01A 041003978-0001A	MASTIC	Tan Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
02 041003978-0002	FLOOR TILE	White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
02A 041003978-0002A	MASTIC	Tan Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Peter Harrison (4)

Stephen Siegel, CIH, Laboratory Manager or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. The test results meet all NELAC requirements unless otherwise specified.

Samples analyzed by EMSL Analytical, Inc. 107 Haddon Ave., WestmontNJ NVLAP Lab Code 101048-0, AHA-LAP, LLC-HLAP Lab 100194, NYS ELAP 10872, NJ DEP 04006